

TOUGHLITE™ SLEEPING PADS

Bestway

ITEM · ARTICLE · ARTÍCULO · ARTIKEL · ARTIKEL · PRODOTTO · ARTYKUL

69643

↔ 183cm x 51 x 7.5cm - 72" x 20" x 3"

⌚ RIDGELITE™ INSULATED REGULAR MUMMY SLEEPING PAD

🛒 0.67kg - 1.49lbs





531G
1.3LBS




4.9

R VALUE
EXTREME WEATHER RATED



1 PUNCTURE-RESISTANT
TOUGHLITE™ TPU

ToughLite™ résistant aux perforations
ToughLite™ resistente a la perforación
Reißfestem ToughLite™
Schaderesistent ToughLite™
ToughLite™ resistente alle forature
Odporny na przebicie ToughLite™




2 I-BEAM CONSTRUCTION

Construction avec profilé en I
Estructura I-Beam
I-trägerkonstruktion
I-balk constructie
Struttura interna con I-Beam
Konstrukcja I-Beam



3 20D RIPSTOP NYLON FABRIC

Nylon indéchirable 20D
Tejido de nailon ripstop 20D
20D-Ripstop-Nylon-Gewebe
20D ripstop nylon stof
Nylon con tessitura ripstop da 20D
Tkanina nylonowa 20D ripstop



4 THERMAZONE™ FEATURES ALUMINIZED
FILM FOR SUPERIOR INSULATION

ThermaZone™ comporte un film aluminisé pour une meilleure isolation
ThermaZone™ incorpora una película aluminizada para un mayor aislamiento
ThermaZone™ verfügt dank aluminisierter Folie über eine hervorragende Isolierung
ThermaZone™ heeft gealuminiseerde folie voor superieure isolatie
Tecnologia ThermaZone™ con membrana in alluminio per una capacità isolante superiore.
ThermaZone™ jest wyposażony w aluminiowaną folię, która zapewnia doskonałą izolację



5 LOW-PROFILE AIR VALVE

Soupape d'air à profil bas
Válvula de aire de perfil bajo
Flachventil
Luchtventiel met laag profiel
Valvola dell'aria a basso profilo
Niskoprofilowy zawór powietrzny

INCLUDES · Inclus · Incluye · Inhalt · Bevat · Include · Zawiera

PUMP SACK

Sac de gonflage servant de pompe - Bolsa de inflado

Kompressionsack - Pompzak

Pompa a sacco - Worek na pompkę

STORAGE BAG

Sac de transport - Bolsa de transporte

Transporttasche - Reistas

Borsa da trasporto - Torba transportowa

REPAIR PATCH

Rustines - Parche de reparación

Reparatur-flicken - Reparatiepatch

Toppa di riparazione - Łatka naprawcza



#69643